

QUOTEBUOY / SAMPLE ESTIMATE

Reconstructed from a public owner-reported service bill

Upload test document - not an original shop invoice

Dockside 20-hour service

Manufacturer: Yamaha
Engine model / year: not reported - leave unknown
Reported location: North Carolina - ZIP not reported
Service mode: Mobile / dockside | Currency: USD
Source publication: October 31, 2025; itemization in owner reply

DESCRIPTION	AMOUNT
Engine oil and filter parts	\$81.85
Engine oil and filter labor 1.5 hours	\$247.50
Miscellaneous fee	\$169.95
Tax	\$33.70

Total \$533.00

Source and testing notes

Amounts and 1.5 billed hours come from the owner's public itemization.
No engine model, service ZIP or parts identifiers have been invented.
The fee was labelled miscellaneous. Travel/disposal details were not provided.
For testing, confirm Yamaha, mobile service and the extracted line amounts.
Do not present this reconstructed document as an original customer invoice.

[View the original public discussion and owner breakdown](#)